

LEO G. ARNETT
160 Greenleaf Blvd.
Morgan City, LA 70380
(985) 631-9290 (HOME)
(985) 518-4038 (Cell)

**PROFESSIONAL
OBJECTIVE:**

To obtain a challenging position utilizing my skills relating to marine construction.

EXPERIENCE:

Contract Inspector.
Over thirty years experience in construction and fabrication of offshore jackets, platforms, pipelines, and topside facilities. Specializing in mechanical completion, visual inspection, NDE inspection, and consulting.

EMPLOYMENT BACKGROUND:

2001- Present **L & L Inspection Services; Morgan City, LA**

BP-Amoco

Mechanical Completion Coordinator Mustang Engineering BP- Amoco Thunder Horse Project at J Ray McDermott Amelia La and Kiewit Offshore Services, Ingleside TX. Mustang Engineering, Opus building, Houston TX. Build all books for Production, Compression, and Generator Modules and also Hull Deck books as per the process system mnemonics. Checked all marine systems to make sure they meet all ABS and Coast Guard regulation requirements. Turn over all documents to commissioning. Visual inspection of structure and piping, NDE trace of secondary steel, review of hydro packages and post weld heat treat records: Thunder Horse Deepwater Development Project.

2000 - 2001

Combisa/Pemex

Inspector for Combisa @ Aransas Pass, TX Gulf Marine Fabrication. Reviewing Hydro Packages for 100% traceability of welding, MTR's, NDE and PWHT for EPC-22 AB1, AB4 and AB5 production platforms.

Shaw Group

Assistant Corporate Quality Assurance Manager Involved with developing procedure qualification records (PQR's) and welding procedure specifications (WPS) according to ASME section 1X for chemical plants, power plants, oil and gas facilities offshore

Combisa/Pemex	Inspector for Inspection Services, Inc. @ Aransas Pass, TX Represented Aker Gulf Marine by performing 100% traceability of welding, NDE, PWHT and MTR'S of Hydro packages for piping on ABI, AB4 and AB5 production platforms
Pemex	QC Inspector for Trispec @ Greens Bayou Fabrication Yard Brown & Root Facilities Houston, TX Visual inspection of structural and piping on offshore Platforms. Involved in walk down of work packs prior to hydro-testing of piping.
1994 - 2000	Global X-Ray & Testing; Amelia, LA
B.P. Exploration	Visual inspection & film interpreting on pipeline
Centana Oil Company	Visual inspection & film interpreting on pipeline
Texaco Bridgeline	Visual inspection & film interpreting on offshore pipeline
El Paso Gas	Visual inspection & film interpreting on offshore pipeline
Texas Eastern	Visual inspection on piping welds for plant expansion & film interpreting to ANSI B31.3
Mobil Jade	Structural and process piping inspection, verified production skids & equipment was in compliance with drawings & specification, coordinated NDE efforts, weld trace & heat trace. Film interpreting to AWS D1.1, ASME Sec VIII, ANSI B31.3

MAJOR JOBS WORKED AT J. RAY MCDERMOTT FABRICATION AND SHIPYARD

1987 - 1994	McDermott Inc.; Morgan City, LA NDE Leaderman, Level III Radiography, coordinating crews, film interpreting. Quality Assurance/Quality Control Welding Inspector
Newport News	Visual inspection & documentation on module.
Tagos Project	Visual Inspection of welding of vessels
Freeport McMoran	Q.C. (pipe mills, heat trace & visual inspection)
Shell "Auger"	Performed visual inspection on all major girder beams
B.P. Explorations	Performed visual inspection on pipe mill rolled tubulars and assured welding was in compliance with welding procedure.
CNG	Q.C. (pipe mills, heat trace, weld trace & visual inspection)
Enserch	Visual inspection of structure & piping on offshore platform
1986 - 1987	MQS Inspection; Morgan City, LA Radiographer - Level III Film Interpreting and Level III Radiography Piping, structural steel, ASME, AWS, ANSI and API Specifications.

FOREIGN EXPERIENCE:

9/96 - 5/97

Enron Oil & Gas: Performed visual inspection on pipe mill rolled tubulars and assured welding was in compliance with welding procedure. Involved in piping , structure and offshore pipelines. Dubia, UAE and Bombay,India

2/98 - 6/98

Amoco Trinidad Oil Company: Performed visual inspection of welds on 36" pipeline and film interpreting API 1104 Trinidad, West Indies

1/00 - 6/00

Mobil Jade Project: Performed visual inspection of all piping and structure field welds made offshore. Equatorial Guinea, West Africa

4/02 7/02

Combisa/Pemex: Reviewing Hydro Packages for 100% traceability of welding, MTR's, NDE and PWHT for EPC 22 AB1, AB4 and AB5 production platforms Ciudad Del Carmen, Mexico

EDUCATION:

Morgan City High School

American Testers (Training)
Radiography - 40 Hours

Total Safety Inc.
Offshore Water Survival Training

PERSONAL DATA:

Marital Status: Married 6 children
Birthdate: January 12, 1956

REFERENCES:

Available upon request